

Menu

HISTORY FILE MAP for year 2001

REALTIME

PLAYBACK

RECALLED REALTIME


RECALLED PLAYBACK

Scheduled Tx off due to low elevation: 2-way to 1-way to 2-way transitions.

296.10:58-11:05: 7m RT 1024bps data lost when DSS63 performed a master equatorial reset.

296.19:46-19:51: 5m RT 1024bps data lost due to NMC interface problem at DSS24. DR G100451 refers.

297.20:39-09:43, 297.21:17-21:28 15m RT 1024bps data lost due to DSS24 antenna halt and subsequent 2-way to 1-way to 2-way transition. DR G100452 refers.



296.02:00-02:02: 2m RT 1024bps data lost because previous day's TSF was used by DSS63 when Tx was switched on. TSF updated to reduce doppler residuals. Extra 1-way to 2-way transition.

297.09:21-09:31, 09:58-10:04, 10:11-10:21: 26m RT 1024bps data lost due to DSS54 antenna halt and subsequent 2-way to 1-way to 2-way transition. DR M100226 refers.

299.12:42-12:47, 13:12-13:13, 13:45-13:48 : Scheduled tracking gap plus associated 2-way to 1-way to 2-way transitions.

Scheduled Tx off. 2-way to 1-way to 2-way transitions.